



# Tech Notes

## Calibration Process for XDRY Ultra-Low Humidity Dry Cabinet

(1) Press the "SET" button for about 5-20 seconds until the Digital Control Panel shows the flashing "P00". (If the panel shows "P88", please go directly to (3).)

(2) Press either "UP" or "DOWN" button to adjust from "P00" to "P88".

(3) Press the "SET" button to enter the calibration mode. The Digital Control Panel shows the initial calibration value is "0.0".

(4) Adjust the humidity offset value by pressing either the "UP" or the "DOWN" buttons. Press the "UP" button to increase the value, and the "DOWN" button to decrease the value. Press the "SET" button after completing the adjustments. The current RH level will be shown on the Digital Control Panel.

E.g. The humidity value on the display is 3%, and the actual humidity level inside the cabinet is 1%, so the offset value is -2.

(5) Contact our customer service at 1-833-265-9440, ext 1001 for any questions.

Max Offset Value 9.9

Min Offset Value -9.9

Initial Offset Value 0